Navajo Abandoned Uranium Mine

Site Screen Report

This form is for use at the site of abandoned uranium mines (AUM) located on Navajo Nation lands. Applicable sites include all mine and mine features that have or have not undergone reclamation by the Navajo Abandoned Mine Lands Reclamation Program, including features, adits, pits and waste piles. Applicable sites also include all AUM sites listed in the USEPA CERCLIS database, all sites listed in the 2008 AUM GIS Report issued by USACOE and USEPA, all AUM sites on allotment lands associated with the Navajo Nation, and any and all AUM sites not listed in any database located on Navajo lands. Reconnaissance of any sites located on lands adjacent to Navajo lands that may be impacting Navajo lands will need to be coordinated with the authorities appropriate to those lands.

The purpose of the form is to ascertain the status and location of the identified AUM site, and record all immediate site information associated with the mine site. Decisions and recommendations on what additional steps are needed will be provided on a separate document.

Mine Name: **Zhealy Tso, Pits**Mine ID: **298**

Navajo AUM Central Region

Prepared by:

Weston Solutions, Inc.

Contract: W91238-06-F-0083

20074.063.017.0020

August 2011

Part I	Site Identification, Location and Status				
Site Names an	nd ID numbers	s as applicable	:		
Mine ID:	298				
Map ID:	C32				
CERCLIS:	NNN000909192				
Navajo Aban	doned Mine L	and Reclamati	ion Program: None	e	
Local name /	Aliases: MP-3	395			
Chapter and	local area: Ch	inle			
County: Apa	che	State: Arizon	a		
Lat/Long:	36.185028214	4 N / -109.473	060877 W		
Nearby road	and highway:	Indian Route	Local Post	Office: Chinle, AZ	
Surface Land below	Status: check	one or more a	and provide owners	hip and contact information	
Tribal Trust Private Bureau of La State			Public lands Tribal Fee Land Allotment Fee land		
Subsurface M	Iineral Rights:				
No informatio	n on subsurface	e mineral rights	s ownership was four	nd in the EPA/AUM Database	
Claim and an	anatan infanm	-4:			

Claim and operator information:

The mine surface land status is classified as Tribal Trust Land. Historical documents identified the operator of the mine as Zhealy Tso and Arizona Giant Mining Company from 1955 to 1958. No additional historical ownership / lease information was identified in the EPA / AUM database.

Number of residential structures within 200 feet of mine: None

Part II Summary of Radiological Readings

Mine ID: 298

Highest gamma radiation measurement: 670,883 counts per minute (cpm)


Background Average: 11,062 cpm **Two Times Background:** 22,124 cpm

Describe any other radiological measurements:

A total of 4,808 gamma radiation measurements were collected from the mine site, ranging from 5,356 cpm to 670,883 cpm. Measurements collected in the vicinity of the waste rock were found at a maximum level of approximately 670,000 cpm. The measurements are represented in Figures 1 and 2.

Distribution Chart and Statistics:

Site Gamma Radiation Statistics				
Number of Readings	4,808			
Minimum (cpm)	5,356			
Maximum (cpm)	670,883			
Mean (cpm)	27,214			
Median (cpm)	10,540			
Standard Deviation	68,885			



Part III Status of Reclamation and Mine Waste

Mine ID: 298

The following information was obtained from the Navajo Abandoned Mine Land Reclamation Program (NAMLRP) Point Features Database:

NAMLRP Status of the mine site: Reclaimed: Unknown Waste Pile onsite: No

NAMLRP Project Number: None

NAMLRP Mine features: 2 Rim Strip / Pits

The following information was obtained from field observations collected during the 2011 site screening:

Provide description and status of all mine sites and features at site. Include all waste piles, adits, pits and other features, and indicate whether they are open, closed, covered, capped, buried or unreclaimed. Indicate approximate size, shape and extent, including description of any reclamation caps. Note condition of all caps.

Observed reclamation work and status:

Adits:

None observed

Waste Piles:

7-8 waste rock piles, approximately 20 - 40 yd³ each

Pits:

None observed

Shafts:

None observed

Other Debris and Mine Features:

Boreholes in southern portion of site

Part IV Site Observations and Environs

Observed Residential Structures (number and human habitation status of structures at the following distances from mine):

0 to 200 feet: None observed

200 feet to 0.25 mile: None observed

Observed Public or Commercial Structures (schools, clinics, Chapter Houses, places of business and any other structures used by members of the community at the following distances from the mine site):

0 to 200 feet: None observed

200 feet to 0.25 mile: None observed

Levels measured around the perimeter(s) of the identified structure(s):

None

Observed Water Sources (number and type of wells and surface water sources that are potentially used for human consumption at the following distances from the mine site):

0 to 0.25 miles: Seasonal tributary to Canyon De Chelly approximately 75 ft W of site

0.25 miles to 4 miles: Canyon De Chelly approximately 1.75 mi S of site

Sensitive Environments (all sensitive environments located within visible range of the mine site, including: wetlands, endangered species, habitats and approximate locations of sites that may be under protection of the government of the Navajo Nation):

The site in located within Canyon De Chelly National Monument

Known Site History (information from interviews with Chapter officials and residents and database review, includes: mine ownership, type of mining operation, period of operation, known amount of production, and any other information provided):

The Zhealy Tso, Pits mine claim consists of an area of 20,080.48 m². The mine surface land status is classified as Tribal Trust Land. Historical documents identified the operator of the mine as Zhealy Tso and Arizona Giant Mining Company from 1955 to 1958. No additional historical ownership / lease information was identified in the EPA / AUM database.

Part V Response Action Summary

Summary of Evaluation Factors:

Accessibility:

Was the mine easily accessible to potential human activity?

Yes

Radiological Measurements:

Were any gamma radiation measurements collected at the mine greater than two times the site-specific background levels?

Yes

Waste Piles:

Were any unreclaimed waste piles observed at the mine with gamma radiation measurements greater than two times the site-specific background levels? Yes

Structures:

Were any structures observed within 200 feet of the mine?

No

Potential Drinking Water Sources:

Were any potential drinking water sources observed within 4 miles of the mine? Yes

Reclamation:

Was the mine reported to be previously reclaimed, or did the mine appear to be reclaimed?

Unknown

Part VI Photos



Photo 1: Mine Site #298; Northwester portion of site



Photo 2: Mine Site #298; Site with Cottonwood Canyon in distance





Photo 4: Mine Site #298; Western edge of site



Photo 5: Mine Site #298; Waste rock piles



Photo 6: Mine Site #298; Discolored rock



Photo 7: Mine Site #298; Waste rock piles



Photo 8: Mine Site #298; Borehole

Part VII Contacts Reports and Information

Name:	Eugene Esplain		
Title or official role (if any):	Navajo EPA Superfund Program		
Telephone number:	(928) 871-7331		
Address:	PO Box 2946, Window Rock, AZ 86515		
Information provided:	Lead Regulatory Agency		
Name			
Name:			
Title or official role (if any):			
Telephone number:			
Address:			
Information provided:			
Name:			
Title or official role (if any):			
Telephone number:			
Address:			
Information provided:			

Figure 1 - Gamma Radiation Measurements, Above Two Times Background
Zhealy Tso, Pits (298)
Chinle Chapter, Navajo Nation





Figure 2 - Gamma Radiation Measurements Zhealy Tso, Pits (298) **Chinle Chapter, Navajo Nation**



- 50,000 100,000 cpm
- 100,000 250,000 cpm
- 250,000 500,000 cpm
- 500,000 1,000,000 cpm

Measured as counts per minute (cpm)

Observed Waste Pile

Observed Structure

// Steep Grade











